



Service Inspection & Sales

JOSH LAWSON - OWNER
MASTER CERTIFIED TECHNICIAN & LICENSED DEALER
HIGHTECHAUTO@GMAIL.COM 503-789-0168
www.HighTechAutoService.com

Customer	Inspection Date	Location Of Inspection		Photos Taken	
Sample Inspection (Joe F****)	Tuesday, August 12, 2008	Vancouver, WA		YES	
Vehicle Identification Number	Year	Make	Model	Trim	Exterior/Interior Color
YV1LZ5645W*****	1998	Volvo	V70XC	AWD	Silver/Tan
Engine	Transmission / Drivetrain	Mileage			
2.4L L5 FI 20V Turbo	Automatic / AWD	154,137			

Inspection Notes/Additional Recommendations
 Needs front axles and brakes. LF door check link (the device that holds the door open) is weak and door closes on its own. Aftermarket hitch

Vehicle Options/Interior/Accessories

	Not Applicable	Good Working Order	Service Required	Additional Comments
Air Conditioning		X		Dual climate - Blows cold
Airbags		X		Factory SIPS - side airbags, airbag lamp illuminates with key on and goes out as designed - no warning lights illuminated
Alarm		X		Factory
Audio		X		Factory
Carpet Condition		X		Carpets and factory floor mats are clean and dry and are in good shape given age
Cigarette Lighter		X		
Dash Condition		X		
Factory Manual		X		In glove box
Fog Lamps			X	R fog lamp INOP
Heated Seats / Mirrors / Steering Wheel		X		Front heated seats and mirrors
Horn		X		
Keyless		X		Factory - only the 1 key and remote?
Lights			X	R fog lamp INOP - Hole/chip in R headlamp housing
Parking Brake		X		
Power Brakes		X		
Power Door Locks		X		Drivers door lock functions okay, but the door lock pin doesn't move when locked and unlocked
Power Mirrors		X		
Power Steering		X		
Power Windows		X		RR window shade clip broken
Rear Defogger		X		
Seat Belts		X		
Seat Condition		X		Clean - given age. Some water staining/marks
Tilt Steering		X		Tilt and telescoping
Trim Condition		X		Door panel material is falling away from all doors - loosing adhesion
Turn Signals		X		
Warning Lights		X		
Weather-Stripping		X		
Wipers		X		



Service Inspections Sales

JOSH LAWSON - OWNER
MASTER CERTIFIED TECHNICIAN & LICENSED DEALER
HIGHTECHAUTO@GMAIL.COM 503-789-0168
www.HighTechAutoService.com

Engine/Transmission

	Not Applicable	Good Working Order	Service Required	Additional Comments
Auto Trans Fluid Condition	X			
Battery Condition		X		
Belts		X		Serpentine belt is newer and is in good shape - Records indicate water pump and timing belt were replaced @ 83K
Component Leaks		X		Oil seepage around pan and turbo housing
Coolant Condition		X		
Electrical System		X		
Hoses		X		
Maintenance Inspection			X	Aftermarket K&N washable filter - DIRTY and needs cleaned
Oil Condition		X		Clean and full - sticker on windshield reads synthetic 5-30 7/20/08 or 153,780
Power Steering Condition		X		
Transfer Case / Axles			X	Both front axles outside boots torn and need replaced - no clicking noticed on test drive
Vacuum Hoses		X		

Structural/Exterior

	Not Applicable	Good Working Order	Service Required	Additional Comments
Body Alignment		X		Overall straight car
Body Condition		X		RR QTR panel has been re-painted near RR door - Original panel no signs of collision damage
Brake Inspection			X	Front Pads 20-30% Rear Pads 20-30% - NEEDS pads all around
Glass Condition		X		
Matching Lugs/Caps		X		
Paint Condition		X		Measures 5 mils throughout - Paint work on RR QTR blended throughout R side - Match and paint quality is very good
Shocks/Suspension		X		
Tire Wear		X		LF - 7/32" RF - 5/32" RR - 6/32" LR - 6/32" (New Passenger Tires @ 10/32" - Replace @ 2/32")
Tires Matching Size/Brand		X		
Visual Emblems, Leaks, Stickers		X		
Wheel Condition		X		Scuffs on several wheels

Road Test

	Not Applicable	Good Working Order	Service Required	Additional Comments
Body/Chassis Integrity		X		
Braking		X		
Cruise Control		X		
Engine Operation/Performance/Acceleration		X		
Engine Start/Idle		X		
Exhaust		X		Aftermarket dual exhaust - fitment appears perfect
Shifting Quality		X		
Steering/Alignment		X		Very slight pull to the right
Transfer Case / Axles		X		No unusual noises noted
Warning lights on, Gauges			X	Scanned for codes - NONE. All I/M emission flags have successfully completed - Service ABS/Trac light came on once but reset - seller states its intermittent